

ERRATA

The Effects of Surface Treatments on Point Contact Transistor Characteristics by J. H. Forster and L. E. Miller, B.S.T.J., **35**, pp. 767-811, July, 1956. Figs. 3, page 776, and 10, page 787, were inadvertently interchanged.

Cable Design and Manufacture for the Transatlantic Submarine Cable System by A. W. Lebert, H. B. Fisher and M. C. Biskeborn, B.S.T.J., **36**, pp. 189-216. Table I, page 3, the material for type B armor wire should be medium steel instead of mild steel. Page 207, the equation for Z_0 should read

$$Z_0 = \frac{b}{\sqrt{\epsilon}} \log \frac{D}{b} \text{ ohms}$$